

Form: IB-EBL-TW Rev. 1.4- 01.02.2014

Preceding report

- none -

Inspection report

Documentation number

Subcontract

EAPR-TW-0070/14

Ausgabe 0 english version

Customer

MAC PARA TECHNOLOGY s.r.o.

Televizní 2615

756 Roznov pod Radhostem

Czech Republic

Order from

07.08.2013

Order entrance

07.08.2013

Contents of order

Determining the function and sufficient strength of a powerd paraglider

Kind of order

simplified

reference

0068

Place of Inspection

87730 Bad Grönenbach, Sitz der Inspektionsstelle

Inspection item

Eden 5 30 - Motor

Serial number

2530-1027

Condition new

LTF 23/05, Pkt. 2.2, Pkt. 4., IA 014 Rev. 1.7 - except shock-/loadtest

Inspection basis

EN 926-1 3.1, 3.2)

Inspection period

07.08.2013

to

07.02.2014

Inspection date

07.02.2014

This inspection report includes 4 pages including cover sheet and 2 plants

This inspection report must be reproduced in its entirety and without change. Excerpts or abbreviations need the written permission of the EAPR GmbH. Documents without signature and stamp are not valid. The cover page and the signature page of this document are provided with the approval stamp of the EAPR GmbH. The accreditations apply to the documents listed in the current certificate of test methods. The list of accredited areas is available on request.



Cause

This inspection is required due to the legal necessity for manufacturers of air sports equipment according to the LuftGerPV to have their product type inspected by an accredited inspection body in accordance with the applicable airworthiness requirements.

Pattern to be inspected:

Eden 5 30 - Motor

1	minimum take-off weight	kg	130
2	maximum take-off weight	kg	160
3	First testflight with		G-Force Moster-185
4	Proven max. strength	daN	-
5	Weight	kg	6
6	Operations Manual, version		Vers. 2.1 - 18.12.213
7	Specifications, version		07.02.2014

Nothing was omitted from the original scope of inspection

The testflights were conducted by EAPR-testpilots

With the exception of the shock and loadest all parts of the inspection work were performed by the EAPR and is not directly part of this inspection report.

Summary

The tested sample is in accordance with the legal requirements (Lufttüchtigkeitsforderungen) regarding the standards, procedures and subchapters listed in -Inspection basis- The inspection basis does not include any applicable airworthiness requirements for this device.

i.A.
Guido Reusch
Inspection and Head of Inspectionbody

Bad Grönenbach.

07.02.2014